# BENCHMARK PROJECT MANAGEMENT (UK) LTD - CASE STUDY

## Title

Small Retaining Wall Reconstruction

## **General Scope:**

Take down and rebuild the length of retaining stone wall while strengthening and also improving drainage.

### Work included:

- Deconstructed stone wall, clean and set aside the stone for reuse
- Build new concrete block retaining structure inclusive of weep holes
- Implementation of perforated pipe and granular drainage to rear of wall
- Excavated line trench and poured new concrete footings
- Reconstruction of set aside stone blocks to match existing style true and plum
- Adjusted existing slabs to accommodate for granular drainage

**Dates:**Jan 2018

Client:
MD Group

**Value:** £60,000.00

#### Innovation:

 The low retaining stone wall on a busy stretch of path was evidently beginning to fail and desperately needed strengthening. It was also found to be missing any type of current foundations or drainage.





## **Customer Satisfaction:**

"What an improvement! It's clearly built to last and we have had nothing but good comments from the nearby residents."

MD Group Project Manager

For more information contact: Lee Probert – Managing Director Telephone No: 01275 545290

